

LANCOM Release Notes

LCOS LX

5.20 RU2

Copyright (c) 2002-2020 LANCOM Systems GmbH, Wuerselen (Germany)

LANCOM Systems GmbH

Adenauerstrasse 20 / B2

52146 Wuerselen

Germany

Internet: <http://www.lancom-systems.com>

August 13th, 2020, CBuersch

Table of Contents

1. Preface	2
2. Device-specific compatibility to LCOS LX	2
3. Advices regarding LCOS LX	3
Information on default settings	3
4. History LCOS LX 5.x / 4.x	4
LCOS LX improvements 5.20.0075 RU2	4
LCOS LX improvements 5.20.0047 RU1	5
LCOS LX improvements 5.20.0039 Rel	5
LCOS LX improvements 5.10.0009 RU2	5
LCOS LX improvements 5.10.0005 RU1	6
LCOS LX improvements 5.10.0004 Rel	6
LCOS LX improvements 5.00.0024 Rel	6
LCOS LX improvements 4.00.0130 RU3	8
LCOS LX improvements 4.00.0108 SU2	9
LCOS LX improvements 4.00.0100 RU1	9
LCOS LX improvements 4.00.0096 Rel	9
5. Known restrictions	10
6. General advice	10
Disclaimer	10
Backing up the current configuration	10

1. Preface

LCOS LX is a completely new developed operating system for selected LANCOM access points. The management and monitoring of the functions is carried out extremely convenient and flexible either via a new intuitive web interface or automatically via the LANCOM Management Cloud.

This document describes the innovations within LCOS LX software release 5.20 RU2, as well as the improvements since the previous version.

Before upgrading the firmware, please pay close attention to chapter 6 “General advice” of this document.

Latest support notes and known issues regarding the current LCOS LX version can be found in the support area of our website

<https://www.lancom-systems.com/service-support/instant-help/common-support-tips/>

2. Device-specific compatibility to LCOS LX

LANCOM products regularly receive major firmware releases throughout their lifetime which provide new features and bugfixes.

LCOS LX release updates including bugfixes and general improvements are available on a regular basis for devices which do not support the latest LCOS LX version. You can find an overview of the latest supported LCOS LX version for your device under

<https://www.lancom-systems.com/products/lcos/lifecycle-management/product-tables/>

3. Advices regarding LCOS LX

Information on default settings

Devices delivered with LCOS LX automatically connect to the LANCOM Management Cloud (LMC). This functionality provides zero-touch installation for new devices. In case you do not want to use the LMC, this feature can be disabled while running the default setup wizard for the initial configuration, or at any time from within LANconfig under Management > LMC. You can manually re-enable the usage of the LMC whenever you want.

4. History LCOS LX 5.x / 4.x

LCOS LX improvements 5.20.0075 RU2

Bugfixes / improvements

- > No IAPP messages were sent when using IEEE 802.1x. This could cause problems when roaming between access points.
- > If the WPA2 key management was configured to 'Fast Roaming' in the encryption settings, the access point could temporarily lose the connection to the WLAN controller.
- > The Wi-Fi modules of a device could not be switched off by an access point profile obtained via WLC. As a result, it was not possible, for example, to use only the first Wi-Fi module on a LANCOM LX-6402 and deactivate the second Wi-Fi module via a WLAN controller.
- > An access point could not obtain a WLC Wi-Fi profile over a VPN connection. As a result, it was not possible to connect and manage the access point via WLC.
- > It was not possible to create an unencrypted SSID via WEBconfig.

LCOS LX improvements 5.20.0047 RU1

Bugfixes / improvements

- In a WLAN controller scenario, no fixed Wi-Fi channel could be assigned to an access point.

LCOS LX improvements 5.20.0039 Rel

New features

- Support for management by LANCOM WLC devices
- Support for LEPS-MAC
- Check of MAC addresses against RADIUS server
- Dynamic VLAN via 802.1X/RADIUS and LEPS
- Wi-Fi time control for SSIDs

Bugfixes / improvements

- If the Auto-Updater is enabled on the device, this is now displayed in the LMC device list.
- If in the device's dashboard in WEBconfig a click on the 'Configure SSID' button was made, the message "No SSID has been created yet" was displayed.
- In WEBconfig, Wi-Fi end devices on the access point were permanently displayed in the status 'Connected', because the 'Idle Timeout' did not work. This was also the case if no SSID was transmitted.
- After pressing the 'Cancel' button in the WEBconfig menu 'LANCOM Management Cloud Coupling', the stored parameters were still displayed instead of being discarded.
- Although a maximum channel width of 40 MHz was configured in the 2.4 GHz settings of a radio module, only a maximum bandwidth of 20 MHz was used.
- In the dialog for scheduling firmware updates a negative value could be entered in the 'End of update time window' field.

LCOS LX improvements 5.10.0009 RU2

Bugfixes / improvements

- In individual cases, an invalid main device password could be set by the LMC in LMC-managed devices with LCOS LX; as a result, these devices could no longer be accessed via the LMC or via local access (e.g. SSH) after a restart. This bugfix avoids this state. To be able to manage a device that was previously in error status locally again, a valid password must be set via the LMC. To do this, start a configuration rollout from the LMC on the affected devices.
- In seldom cases, a LANCOM LW-500 restarted with the firmware available in the second FirmSafe slot.

LCOS LX improvements 5.10.0005 RU1

Bugfixes / improvements

- › In individual cases, the configuration of LW- and LX series devices was not stored persistently, and HTTPS access was not possible.

LCOS LX improvements 5.10.0004 Rel

New features

- › Support for WPA3
- › The LANCOM LW-500 supports the features of LCOS LX 5.00:
 - › Automatic software updates via auto-updater
 - › Band Steering (for IEEE 802.11v-capable and legacy clients)
 - › Fast Roaming based on IEEE 802.11r
 - › IEEE 802.1X pre-authentication
 - › LEPS-U (LANCOM Enhanced Passphrase Security - User)

Bugfixes / improvements

- › After a firmware update in WEBconfig the message 'Access Denied' was displayed.
- › When calling the 'Monitoring' menu in the Safari web browser, the graphs were displayed without content.

LCOS LX improvements 5.00.0024 Rel

New Features

- › Support for Wi-Fi 6
- › Automatic software updates via Auto Updater
- › Band Steering (for IEEE 802.11v capable and legacy clients)
- › Fast Roaming as per IEEE 802.11r
- › 802.1X Pre-Authentication
- › LEPS-U (LANCOM Enhanced Passphrase Security - User)
- › Support for LLDP
- › Support for SNMPv3
- › Support for LANmonitor
- › IEEE 802.1X supplicant for the Ethernet interface

Bugfixes / improvements

- › An offline configuration created by LANconfig could not be saved to the LANCOM LW-500.
- › While performing an environment scan in WEBconfig the table was not populated with scan results.
- › A LANCOM LW-500 could not be restarted from within the LANCOM Management Cloud (LMC).
- › Only one IPv6 address was shown in the network settings, although multiple IPv6 addresses had been allocated to the device.
- › Wi-Fi devices were not stored to the station table if the device name contained special characters. Now all characters are accepted and thus all devices are displayed in the device list.
- › The displayed idle timeout of a Wi-Fi device was, against the usual process for other LANCOM access points, incremented instead of decremented.
- › When accessing a device by console with a non-existing user the message "admin not found" was displayed.
- › Entering a WPA2 Wi-Fi key with less than 8 characters caused the message "Wrong charset". Now a message appears showing the hint to use at least 8 characters.
- › The output of a table after using the command "set ?" was arbitrarily sorted. Now the output is displayed in the correct column order, starting with column 1.
- › The following display- and functional issues on Safari- and Chrome browsers have been fixed:
 - › A device could not be restarted, because the restart button was not active.
 - › A device could not be reset to factory defaults.
 - › A display issue when using the bandsteering function has been solved.
- › When the path "/WLAN/Radio" was reset to default settings by using the command "default", the Wi-Fi module 2 was configured to 2.4 GHz, although this frequency band is not supported by the module.
- › After selecting a radar signal it could happen that the LANCOM LW-500 changed the channel to a channel neighboring the weather radar range (120 bis 128). When using 80 MHz channel width this led to overlapping with the weather radar channel range. It is now ensured that channel overlapping is no longer possible.
- › In the dashboard the number of Wi-Fi devices connected to the 2.4 GHz band was not displayed correctly.
- › The names of the encryption profiles were prefixed by a random sequence of 5 letters and numbers. This resulted in limited readability. This random sequence is no longer added.
- › When using IEEE 802.1X the LANCOM LW-500 always reported the Wi-Fi standard IEEE 802.11b on the RADIUS authentication request in the field 'Connect-Info', if the Wi-Fi device was connected per IEEE 802.11ac. The LANCOM LW-500 does no longer report a Wi-Fi standard in the 'Connect-Info' field.

LCOS LX improvements 4.00.0130 RU3

New Features

WEBconfig

- The "Connected clients" table on the dashboard now contains a reload button.
- The "Neighborhood" and "Wi-Fi configuration > Technology" pages now contain the timestamp of the last neighborhood scan.
- The "Wi-Fi configuration > Technology" page now also contains a button for starting the neighborhood scan and thus for determining the neighboring SSIDs.

Generic

- The "default" command for recursively resetting configuration paths to their default values is now available on the CLI.

Bugfixes / improvements

- The number of operating days was missing in the information on the operating time of a device.
- The station table in the dashboard of the web interface was not queried regularly. This meant that newly connected stations were not displayed in the dashboard.
- An IPv6 address obtained via Router Advertisement was not displayed in the network settings.
- The graphical display for WLAN and LAN data throughput was lower than the real values.
- A maximum of 200 clients could be displayed in the station table.
- If the 2.4 GHz mode was configured to "IEEE 802.11g/n (Mixed)" in the radio settings, the access point continued to transmit with IEEE 802.11b.
- The counter in the **Status/LAN/Byte-Transport/** table was only 10 characters long. If the maximum value was exceeded, the affected interface disappeared from the table. In such a case, no more data for the affected interface was displayed in the LMC or in WEBconfig.
- A click into an input field in the WLAN configuration offered the "Save" dialog, although no configuration changes had been made yet.
In addition, after switching to the WLAN configuration in WEBconfig and subsequently leaving the WLAN configuration without making any configuration changes, the user was informed via popup about unsaved changes.
- No QR code for unencrypted SSIDs was displayed.
- If a firmware update was initiated via an IPv6 connection, the firmware update ran successfully. However, the web interface was not updated and remained in status **Firmware update in progress**.
- After changing the main device password in WEBconfig the configuration was not written back to the device. Thus the old password was still active after a restart.
- The mode **802.11b/g/n** was displayed in the WLAN dashboard and on the console when **802.11g/n** was used.

LCOS LX improvements 4.00.0108 SU2

Bugfixes / improvements

- Multiple vulnerabilities have been fixed which could cause linux-based systems to crash (CVE-2019-11477, CVE-2019-11478, CVE-2019-11479). See also the general security information on the LANCOM website:
<https://www.lancom-systems.com/service-support/instant-help/general-security-information/>

LCOS LX improvements 4.00.0100 RU1

New Features

- The username „root“ is now predefined on the WEBconfig login screen.

Bugfixes / improvements

- After having received an IAPP message of an adjacent access point, clients which were connected by roaming have not been deleted from the station table.

LCOS LX improvements 4.00.0096 Rel

New Features

- Initial version supporting the LANCOM LW-500

5. Known restrictions

- When using both LAN ports for passing through data traffic only untagged data traffic or data traffic tagged with the management VLAN tag is passed through.
- Local configuration changes are not transferred to the LMC.
- Scripting the device by the LMC is currently not supported.

6. General advice

Disclaimer

LANCOM Systems GmbH does not take any guarantee and liability for software not developed, manufactured or distributed by LANCOM Systems GmbH, especially not for shareware and other extraneous software.

Backing up the current configuration

Before upgrading your LANCOM devices to a new LCOS LX version it is essential to backup the configuration data!

Due to extensive features it is **not possible to downgrade** to a previous firmware without using the backup configuration.

Please see the LCOS LX reference manual for instructions on how to upgrade the firmware.

We strongly recommend updating productive systems in client environment only after internal tests.

Despite intense internal and external quality assurance procedures possibly not all risks can be eliminated by LANCOM Systems.