

LANCOM Release Notes for XS series switches

LCOS SX

5.10 RU1

Copyright © 2002-2021 LANCOM Systems GmbH, Wuerselen (Germany)

LANCOM Systems GmbH
Adenauerstrasse 20 / B2
52146 Wuerselen
Germany

Internet: <http://www.lancom-systems.com>

July 15th, 2020, CBuersch

Table of Contents

1. Preface	2
2. New features, improvements, and history	3
LANCOM XS series - LCOS SX 5.10.0025 RU1	3
LANCOM XS series - LCOS SX 5.10.0013 Rel	4
LANCOM XS-5xxx - LCOS SX 5.00.0117 RU2	5
LANCOM XS-5xxx - LCOS SX 5.00.0116 RU1	5
3. Common advice	6
Disclaimer	6
Support notes & known issues	6

1. Preface

The LANCOM family of operating systems—LCOS, LCOS SX, LCOS LX, and LCOS FX—forms the trusted basis for the entire LANCOM range of products. Within the scope of the hardware specified by the products, the latest firmware version is available for all LANCOM products and is offered by LANCOM Systems for download free of charge.

LCOS SX 5.x is the operating system for all LANCOM switches of the XS series. In the context of the hardware given by the products the at a time latest LCOS SX 5.x version is available for all LANCOM switches of the XS series and is available free of charge for download from LANCOM Systems.

For all LANCOM switches of the GS-13xx, GS-23xx, and GS-3xxx series the LCOS SX 3.x / 4.x operating system is pursued. You can find the release notes for these series as usual on the LANCOM website in the download area of the respective switch.

This document describes the innovations within LCOS SX software release 5.10 RU1, as well as the improvements since the previous version.

Devices delivered with LCOS SX 5.00 or higher automatically connect to the LANCOM Management Cloud (LMC). This functionality provides zero-touch installation for new devices. In case you do not want to use the LMC, this feature can be disabled at any time on the device's WEBconfig under "Configuration > LMC". You can manually re-enable the usage of the LMC whenever you want.

2. New features, improvements, and history

LANCOM XS series - LCOS SX 5.10.0025 RU1

Bug fixes

- It could happen that the client for connecting to the LANCOM Management Cloud (LMC) terminated itself after pairing with the LMC. In addition it was not possible to restart the client via command line interface.
- If the switch was configured as a DHCP client and could not establish a connection to the LMC, no DHCP renew was performed. In this case, the error message "No DHCP server detected" appeared in the LMC control state trace.
- It could sporadically happen that the switch could not read the information of plugged SFP modules.
- On the LANCOM XS-6128QF it could happen that only a speed of 10 Gbps was detected when using SFP-DAC25 cables on the rear stacking ports (board type 3 or 4).
- If errors occurred when rolling out a configuration via the LMC, it could happen that these were transmitted to the LMC incompletely or not at all.
Furthermore, a race condition was fixed that prevented a valid VLAN configuration from being rolled out via the LMC.
- After changing the management VLAN on a switch, it did not perform a DHCP renew and was therefore no longer accessible for connections. A manual DHCP renew request had no effect.

LANCOM XS series - LCOS SX 5.10.0013 Rel

New features

- Full Layer-3 functionality through VRRP and policy-based dynamic routing via OSPF v2 / OSPF v3 (all LANCOM XS switches) and BGP4 (XS-6128QF only)
- The 'Next Active' firmware can now be set on all switches simultaneously in the stack via WebGUI.
- AES-192/256 and SHA-2 algorithms are now supported. This enables SNMPv3 connections with LANmonitor.

Bug fixes

- In the logging of the LANCOM XS-6128QF it could happen that due to a readout error an incorrect temperature was determined and this was output as an alarm message.
- In a stacking scenario, operating data such as fan speeds, CPU temperature, etc. were only displayed by the manager device.
- The IP routing table of a switch was not read out completely via SNMP, which resulted in the configured local networks not being displayed in LANmonitor, for example.
- LACP was found in WEBconfig in the path 'Switching / Port Channel'. The menu 'Port Channel' has now been renamed to 'Port Channel/LAG' so that this menu corresponds to the corresponding menu of the other LANCOM switches.
- If the MTU was changed on several switch ports at the same time, the correct MTU was only set on the first selected port. On the remaining ports, a value corresponding to the stored MTU + 18 was set.
- If the 'Stacking' and 'Loop Protection' functions of a stacking port were configured via SNMP, this resulted in these ports no longer being visible in the configuration. When configuring the 'Loop Protection' of a stacking port via web interface, this port was subsequently also no longer visible in the configuration.
- Via console and via web interface it was possible to add unsupported switch types to a stack whose stacking ports are not compatible with each other (e.g. an XS-5110F with an XS-5116QF).
- If routing was activated for a VLAN after it was created and further VLAN settings were made, the view in the web interface no longer updated and froze. Furthermore, the connection to the web interface was completely lost and it was no longer possible to establish a connection via SSH.
- It could happen that the SFP inventory data was read out incorrectly or incompletely via CLI.

LANCOM XS-5xxx - LCOS SX 5.00.0117 RU2

Bug fixes

- It could happen that incorrect readout data of the module temperature was generated due to incorrect timing on the I2C bus. As a result, the "Fan LED" (status of the fan) on the front of the switch turned red and the function of the switch was affected. However, after a restart, the switch worked normally again.
- The I2C bus was also completely disturbed in rare cases, resulting in incorrect output values, such as incomplete inventory data of the SFP+ modules. This disturbance was also corrected by correcting the I2C timings.

LANCOM XS-5xxx - LCOS SX 5.00.0116 RU1

This release update is the first for the new LANCOM aggregation switches of the XS-5xxx series.

New features

- Added the option to redirect HTTP to HTTPS without disabling HTTP completely.
- Using the CLI command 'erase permanent-storage' it is now possible to reset all persistent data to factory defaults. This means that all settings, sensitive data, and certificates are deleted. After executing this command it is possible to pass the switch on to another customer or partner without hesitation.
- Until now, not all monitoring information from the switches was recorded in the LANCOM Management Cloud. From this version on all information can be read out as usual in the LMC.
- When tunneling terminal access from the LMC, it is no longer necessary to enter user name and password. This redundant query has been removed.

Bug fixes

- During the LANconfig device search via TFTP broadcast it could sporadically happen that a switch answered the request with an 'ICMP port unreachable'. As a result the switch was not found during a device search.
- If the DHCP client of the switch was active, static IP entries were not saved in order to be added to the configuration and become active when deactivating the DHCP client.
- Synchronization of the firmware in the stack did not work if a stack member who joined a stack joined another stack with a higher firmware version.
- A vulnerability existed in OpenSSH 8.3p allowing for potential Denial of Service (DoS) attacks and remote execution of malicious code (CVE-2020-15778).
This vulnerability in the OpenSSH library has been fixed.
- Synchronization of the SSH host key in a stacking network to all members did not work. As a result, if management was moved to another switch while keeping the IP address of the stacking group, an SSH client login to the switch would result in an unknown host key warning message.

3. Common advice

Disclaimer

LANCOM Systems GmbH does not take any guarantee and liability for software not developed, manufactured or distributed by LANCOM Systems GmbH, especially not for shareware and other extraneous software.

Support notes & known issues

Latest support notes and known issues regarding the current LCOS SX version can be found in the download area of our website: [Common support hints](#)