# Release Notes

# LANtools 10.90 Rel

# Table of contents

02	1.	Preface

03	2.	New features, improvements, and history
03		LANconfig 10.90.0045 Rel / LANmonitor 10.90.0016 Rel
04		LANconfig 10.90.0038 RC3 / LANmonitor 10.90.0014 RC3
05		LANconfig 10.90.0029 RC2
06		LANconfig 10.90.0023 RC1 / LANmonitor 10.90.0011 RC1
07	3.	Important advice
07		Disclaimer





#### 1. Preface

The LANtools are a comprehensive set of free management & monitoring tools for a detailed configuration and monitoring of LANCOM devices.

This document describes the innovations within LANtools version 10.90 Rel, as well as the improvements since the previous version.

#### Note

LANCOM LANtools support Microsoft Windows 7, Windows 8, Windows 10, Windows 11, Windows 2008 Server, Windows Small Business Server 2011, Windows Server 2012, Windows Server 2012 R2, Windows Server 2016, and Windows Server 2019 (all 32- and 64-bit versions).

For Windows Vista and Windows 2008 Server you will find user data under \Users\ USER\AppData\Roaming\LANCOM\ and the application files under \ProgramData\ LANCOM\.

When upgrading to LANtools 8.50 or newer, all existing user- and application data is moved to the corresponding folders.



## 2. New features, improvements, and history

## LANconfig 10.90.0045 Rel / LANmonitor 10.90.0016 Rel

#### **New features**

#### **LANconfig**

→ The Internet Wizard has been updated and expanded to include current providers.

#### **Improvements**

→ A new setup wizard is available for LANCOM routers with a cellular modem, which can be used to configure failure protection for Telekom Business connections (Telekom NonStop network).

#### **Bug fixes**

#### **LANconfig**

- → In the setup wizard for configuring a DS-Lite Internet connection, the input field for specifying a target interface was missing.
- → When configuring a LANCOM WLC-60, only a maximum of 30 entries could be made in the access point table.
- → For LANCOM routers in which a LANCOM AON module was used in the SFP port, the mode 'FD1000b-F' could not be set.
- → With LCOS 10.80 RU9, the configuration of 1800 series routers could not be read or written via the serial USB-C configuration interface using LANconfig. Furthermore, the device search via the serial interface using LANconfig did not work.





## LANconfig 10.90.0038 RC3 / LANmonitor 10.90.0014 RC3

## **Bug fixes**

#### **LANconfig**

→ On LANCOM routers with only one logical DSL interface (e.g. LANCOM 1780EW-4G+), an inconsistent interface designation for the Ethernet OAM interfaces meant that configurations could not be rolled out to the LMC.

#### **LANmonitor**

→ No WWAN connections were displayed in LANmonitor 10.90 if a LANCOM router was operated with an LCOS 10.90 version.





# LANconfig 10.90.0029 RC2

## **New features**

 $\rightarrow$  For some LANCOM devices, an error in the OAM interface table could cause a configuration rollout to the LMC to fail.





# LANconfig 10.90.0023 RC1 / LANmonitor 10.90.0011 RC1

## **New features**

 $\rightarrow$  Support for LCOS 10.90





## 3. Important advice

#### **Disclaimer**

LANCOM Systems GmbH does not take any guarantee and liability for software not developed, manufactured or distributed by LANCOM Systems GmbH, especially not for shareware and other extraneous software.





