

Release Notes

LANtools 10.94 Rel

Table of contents

02	1. Preface
03	2. New features, improvements, and history
03	LANconfig 10.94.0031 Rel / LANmonitor 10.94.0011 Rel
04	LANconfig 10.94.0024 RC2 / LANmonitor 10.94.0007 RC2
05	LANconfig 10.94.0015 RC1 / LANmonitor 10.94.0005 RC1
06	3. Important advice
06	Disclaimer



1. Preface

The LANtools are a comprehensive set of free management & monitoring tools for a detailed configuration and monitoring of LANCOM devices.

This document describes the innovations within LANtools version 10.94 Rel, as well as the improvements since the previous version.

Note

LANCOM LANtools supports the Microsoft operating systems Windows 10, Windows 11, Windows Server 2016, Windows Server 2019, Windows Server 2022, and Windows Server 2025.

For Windows Vista and Windows 2008 Server you will find user data under \Users\USER\AppData\Roaming\LANCOM\ and the application files under \ProgramData\LANCOM\.

When upgrading to LANtools 8.50 or newer, all existing user- and application data is moved to the corresponding folders.



2. New features, improvements, and history

LANconfig 10.94.0031 Rel / LANmonitor 10.94.0011 Rel

Bug fixes

LANconfig

- When creating a new profile for the Advanced VPN Client using the setup wizard 'Set up dial-up access (RAS, VPN)' in LANconfig, the subnet mask was set to 0.0.0.0 in a new IPv4 pool instead of leaving it blank.
- The 'Set up Internet access' wizard in LANconfig incorrectly activated the DHCPv4 client when creating a DS-Lite connection.



LANconfig 10.94.0024 RC2 / LANmonitor 10.94.0007 RC2**Bug fixes****LANconfig**

- On LANCOM devices with firmware lower than LCOS 10.50, reading the configuration via HTTPS failed.
- In the 'Interfaces / LAN / 802.1X Authenticator for ETH Ports' dialog, the option to reference an existing RADIUS server was missing.
- After activating the LANCOM Security Essentials Option, no corresponding action objects were created in the IPv4 firewall.
- When the 'Enforce device password policy' option was enabled, it was not possible to create user accounts for additional administrators. The user accounts of existing administrators could no longer be edited.
- In the WireGuard peer configuration, it was not possible to enter a hyphen in the 'Endpoint' field.
- The port speed '10 Mbps half duplex' could not be set in the Ethernet port configuration.



LANconfig 10.94.0015 RC1 / LANmonitor 10.94.0005 RC1**New features****LANconfig / LANmonitor**

- Support for LCOS 10.94



3. Important advice

Disclaimer

LANCOM Systems GmbH does not take any guarantee and liability for software not developed, manufactured or distributed by LANCOM Systems GmbH, especially not for shareware and other extraneous software.

