

Information regarding

LANCOM Management System (LCMS) Version 9.24 Rel

Copyright (c) 2002-2016 LANCOM Systems GmbH, Wuerselen (Germany)

LANCOM Systems GmbH does not take any guarantee and liability for software not developed, manufactured or distributed by LANCOM Systems GmbH, especially not for shareware and other extraneous software.

LANCOM Systems GmbH
Adenauerstrasse 20 / B2
52146 Wuerselen
Germany

Internet: <http://www.lancom.eu>

05.09.2016, CBuersch

Table of Contents

1. Preface.....	2
Note	2
2. New Features, Improvements and History	3
LANconfig improvements 9.20.0127 RU1 ▶ 9.24.0023 Rel.....	3
LANmonitor improvements 9.20.0090 RU1 ▶ 9.24.0011 Rel	3
LANconfig improvements 9.20.0109 Rel ▶ 9.20.0127 RU1.....	3
LANmonitor improvements 9.20.0080 Rel ▶ 9.20.0090 RU1	3
LANconfig improvements 9.20.0099 RC2 ▶ 9.20.0109 Rel.....	4
LANmonitor improvements 9.20.0075 RC2 ▶ 9.20.0080 Rel	4
LANconfig improvements 9.20.0090 RC1 ▶ 9.20.0099 RC2.....	4
LANmonitor improvements 9.20.0067 RC1 ▶ 9.20.0075 RC2	4
LANconfig improvements 9.18.0035 RU3 ▶ 9.20.0090 RC1.....	4
LANmonitor improvements 9.18.0020 RU2 ▶ 9.20.0067 RC1	4

1. Preface

LCMS, consisting of LANconfig and LANmonitor, serves for the administration of all Wireless LAN Access Points and Routers. The at a time latest versions are available for all LANCOM products. You can download it for free at <http://www.lancom-systems.com>

This document describes the innovations within version 9.24 Rel, as well as the modifications since version 9.20.

Note

LCMS supports Windows Vista, Windows 7, Windows 8, Windows 10, Windows 2008 Server, Windows Server 2011 (all 32- and 64-bit versions) and Windows Server 2012 & Windows Server 2012 R2.

For Windows Vista and Windows 2008 Server you will find user data under \Users\USER\AppData\Roaming\LANCOM\ and the application files under \ProgramData\LANCOM\.

When upgrading to version 8.50 or newer existing user- and application data is moved to the corresponding folders.

2. New Features, Improvements and History

LANconfig improvements 9.20.0127 RU1 ► 9.24.0023 Rel LANmonitor improvements 9.20.0090 RU1 ► 9.24.0011 Rel

New Features:

LANconfig:

- Support for new devices LANCOM 730VA and LN-630acn dual Wireless
- With activated password policy a warning message will be displayed if the device's main password has not been set

(W)LANmonitor:

- Reworked Public Spot display

Bugfixes / Improvements:

LANconfig:

- Modified help texts

LANconfig improvements 9.20.0109 Rel ► 9.20.0127 RU1 LANmonitor improvements 9.20.0080 Rel ► 9.20.0090 RU1

New Features:

- The All-IP wizard supports now DeutschlandLAN NFON
- Support for the LANCOM Battery Pack

Bugfixes / Improvements:

LANconfig:

- Modified help texts
- Incorrect default values have been corrected
- The remote station description within the DNS forwarding table can now consist of more than 31 characters
- Configuration data can be written again when using an HTTP(S) proxy with NTLM authentication
- Fixed a bug which lead to trace files with a file size of 0 bytes

(W)LANmonitor:

- No CA information is displayed if the device has no CA
- The call list is now displayed more clearly

LANconfig improvements 9.20.0099 RC2 ▶ 9.20.0109 Rel
LANmonitor improvements 9.20.0075 RC2 ▶ 9.20.0080 Rel

Bugfixes / Improvements:

LANconfig:

- Modified help texts
- Multiple entries with the same MAC address can be stored in the BootP table again
- BGP can be configured on an IAP-4G again

(W)LANmonitor:

- Point-to-Point partners and WLAN information is displayed again

LANconfig improvements 9.20.0090 RC1 ▶ 9.20.0099 RC2
LANmonitor improvements 9.20.0067 RC1 ▶ 9.20.0075 RC2

Bugfixes / Improvements:

LANconfig:

- IKEv2 remote stations are now displayed within the firewall stations object list
- Adding the SNMP community „Default“ does not delete all entries
- An encrypted configuration file can be uploaded to the device by “Drag&Drop”

(W)LANmonitor:

- If a WLAN interface is disabled, no information for this interface (e.g. channel load) is displayed
- WLC information display is correct

LANconfig improvements 9.18.0035 RU3 ▶ 9.20.0090 RC1
LANmonitor improvements 9.18.0020 RU2 ▶ 9.20.0067 RC1

New Features:

LANconfig:

- Added a link to the online documentation
- Support for new devices: LANCOM GS-2326P+

(W)LANmonitor:

- WLANmonitor can be started temporarily
- WLANmonitor can be started from LANmonitor