

Information regarding

LANCOM GS-1224P

Copyright (c) 2002-2013 LANCOM Systems GmbH, Wuerselen (Germany)

LANCOM Systems GmbH does not take any guarantee and liability for software not developed, manufactured or distributed by LANCOM Systems GmbH, especially not for shareware and other extraneous software.

LANCOM Systems GmbH
 Adenauerstrasse 20 / B2
 52146 Wuerselen
 Germany

Internet: <http://www.lancom.eu>

25.07.2013, CBuersch

Table of Contents

1. Preface.....	2
Warning hints	2
Hint for Software Update from 1.37 Rel to 2.11 Rel.....	2
2. Known Issues	2
3. New Features, Improvements and History	3
LANCOM GS-1224P improvements 1.37 Rel ► 2.11 Rel.....	3
4. Comments	4

1. Preface

Warning hints

Before upgrading your device to a new firmware it is essential to backup your device's configuration. Due to extensive features it is not possible to downgrade to a previous firmware without using the backup configuration.

Hint for Software Update from 1.37 Rel to 2.11 Rel

When updating the firmware from 1.37 Rel to 2.11 Rel, firmware 2.08 has to be flashed before. A direct update is **not** possible.

2. Known Issues

Latest support notes and known issues regarding the current LCOS version can be found in the download area of our website <http://www.lancom-systems.eu/Common-Support-Hints.64.0.html>

3. New Features, Improvements and History

LANCOM GS-1224P improvements 1.37 Rel ► 2.11 Rel

Bugfixes / Improvements:

- PoE can be disabled for single ports again
- Removed typos in the webconfig interface
- While pinging to a non-existing IP address, the refresh button shows the current state
- An SNMP walk runs until completion

4. Comments

In principle, we suggest upgrading the firmware of your device only if you are in need of the latest features.

Please note that different firmware files might be available for your device. Further information can be found in the file README.PDF in the download area of our homepage.