

Information regarding

LANCOM VP-100 3.04.0012 Release

Copyright (c) 2002-2009 LANCOM Systems GmbH, Wuerselen (Germany)

LANCOM Systems GmbH does not take any guarantee and liability for software not developed, manufactured or distributed by LANCOM Systems GmbH, especially not for shareware and other extraneous software.

LANCOM Systems GmbH Adenauerstrasse 20 / B2 52146 Wuerselen Germany

Internet: http://www.lancom.eu

05.10.2009, CBuersch

Table of Contents

- 1. Information
- 2. New Features, Changes & History



1. Information

Warning hint before upgrading the firmware

Before upgrading the firmware it is essential to backup the configuration file and phonebook of your phone!

Without backup a downgrade to a previous firmware version is no longer possible.

After the firmware upgrade please reset your LANCOM VP-100 to factory defaults and reconfigure your SIP account.

Without this step the firmware changes can not be applied completely.

2. New Features, Changes & History

LANCOM VP-100 changes 3.03.0098 RC1 -> 3.04.0012 Release

Bugfixes / Changes:

- On two simultaneously incoming RTP streams to the same SIP subscriber (e.g. switching with music on hold from a media server), audio data is transmitted in both directions
- VP-100 supports SIP server REINVITEs for calls on hold with delayed SDP negotiation
- Faulty hold music is set to silence
- The range of values for the SIP time interval (RTP timeout) is extended to 1.000 seconds

LANCOM VP-100 changes 3.03.0056 -> 3.03.0098 RC1

New Features:

- Configurable call behaviour (Call waiting, put through)
- Mutated vowels can be entered via keypad

Bugfixes / Changes:

- Additional menu languages
- Extended setup wizard
- Improvements on CVS import to the VP-100 phonebook
- Stability improvements
- Fixed problems on connection establishmant
- Fixed issue on saving the phone number of an unanswered call to the phone book
- Improved selection of characters and digits when setting up via phone keypad
- Added selection of canonical numbers from the phone book
- Modified display of unanswered calls, if the VP-100 is registered directly to SIPGATE
- Improved registration when using a Nokia Siemens Network Switch
- Improved silence detection
- Improved configuration of call forwarding and outside line access
- "NOTIFY-Requests" modified acc. RFC"
- Modified display of the daylight saving time in WEBconfig
- Improvements for Auto Update
- After a successful transfer the call number of the connected subscriber is shown on the display
- Using a VP-100 while upgrading the firmware does no longer lead to a crash
- If a saved configuration is transferred to the device, the success message is shown in the selected language
- If all lines are busy, the display shows "busy"



LANCOM VP-100 changes 3.03.0052 -> 3.03.0056

Bugfixes / Changes:

- Reworked display menu texts
- Improved codec list configuration to avoid multiple selection of the same codec

LANCOM VP-100 changes 3.03.0049 -> 3.03.0052

Bugfixes / Changes:

- The delay for call redirection is configurable via Web interface
- Improved handling when specifying a DNS server via display
- 255 can be used as network segment in an IP network (e.g. 192.168.255.0/24)
- Internal services of the phone are monitored by watchdogs
- Stability improvements

LANCOM VP-100 changes 3.03.0045 -> 3.03.0049

Bugfixes / Changes:

- The ,Refered By' field is utilized according to RFC 3892
- The firmware version is shown similar to LANconfig in the WEB interface
- The PPPoE username is extended to 64 characters
- Automatical firmware update is functional
- Phone book entries which contain mutated vowels are correctly imported
- A held call may be retrieved using the flash button, if the secondary call could not be established
- First of all, the Setup-Wizard asks for language settings
- Call connections are no longer disrupted by the VP-100
- During calls billing time and destination are shown in the display
- Phonebook import/export from/to CSV format