LANCOM
Systems

Information

LCOS Update for LANCOM XAP-40-2

LANCOM Systems GmbH
Adenauerstrasse 20 / B2
52146 Würselen
Germany

Internet: http://www.lancom.de

28.04.2008, CBuersch

1.   Introduction

This area contains current **L**AN**C**OM **O**perating **S**ystem (short: LCOS)-versions and information about your **LANCOM XAP-40-2** Router.

If you like to update your device, please install the current LANtools-version first. After that you can start LANconfig and with the button „Firmware-Upload" you are able to load the new LCOS-version into your device.

There may be several files in your device's directory:

- **latest firmware version**
- **previous firmware version**
- **firmware for use with router options**
- **different firmware files for Annex A /Annex B devices**
- **converter firmware**
- **manuals / description files**

Please note that not all above mentioned files may exist for each device. There may furthermore be different combinations of the above mentioned files available on FTP, WEB or CD.
Normally you will find the latest files on our FTP- or webserver. Please pay also attention to the chapter "Available files" in this document.

Revision information of earlier LCOS-versions is recorded in the Release Notes, which you will find in the "Documentation" area (filename: LCOS-xxx.PDF, whereas xxx stands for the LCOS version number).

2.   Available files

This area contains the following files (xxx is equal to the LCOS version number):

Readme-XAP.pdf   this file

LC-XAP-x.xx.xxxx.upx   Firmware-file for LANCOM XAP-40-2
LC-XAP-CV-x.xx.xxxx.upx   Converter-file for LANCOM XAP-40-2
LC-XAC-XAP-IAP54-MANUAL-EN.pdf   Manual for LANCOM XAP-40-2