

LANCOM Release Notes

LANtools 10.30 RC2

Copyright (c) 2002-2019 LANCOM Systems GmbH, Wuerselen (Germany)

LANCOM Systems GmbH
Adenauerstrasse 20 / B2
52146 Wuerselen
Germany

Internet: <http://www.lancom-systems.com>

March 15th, 2019, CBuersch

Table of Contents

1. Preface	2
2. New features, improvements, and history	3
LANconfig 10.30.0013 RC2 / LANmonitor 10.30.0005 RC 2	3
LANconfig 10.30.0009 RC1 / LANmonitor 10.30.0002 RC 1	4
3. Important advice	5
Disclaimer	5

1. Preface

The LANtools are a comprehensive set of free management & monitoring tools for a detailed configuration and monitoring of LANCOM devices.

This document describes the innovations within LANtools version 10.30 RC2, as well as the improvements since the previous version.

Note

LANCOM LANtools support Windows 7, Windows 8, Windows 10, Windows 2008 Server, Windows Small Business Server 2011, Windows Server 2012, Windows Server 2012 R2, and Windows Server 2016 (all 32- and 64-bit versions).

For Windows Vista and Windows 2008 Server you will find user data under \Users\USER\AppData\Roaming\LANCOM\ and the application files under \ProgramData\LANCOM\.

When upgrading to LANtools 8.50 or newer, all existing user- and application data is moved to the corresponding folders.

2. New features, improvements, and history

LANconfig 10.30.0013 RC2 / LANmonitor 10.30.0005 RC 2

Bugfixes / improvements

LANconfig

- › Opening the table for IPv4 firewall rules in the menu “Firewall > IPv4 > Rules” caused a sudden LANconfig application close.

LANmonitor

- › A DHCP lease of the type “dynamic allocation” was erroneously shown in LANmonitor as “Bootp”.

LANconfig 10.30.0009 RC1 / LANmonitor 10.30.0002 RC 1

New features

LANconfig / LANmonitor

- > Initial version supporting LCOS 10.30 RC1

3. Important advice

Disclaimer

LANCOM Systems GmbH does not take any guarantee and liability for software not developed, manufactured or distributed by LANCOM Systems GmbH, especially not for shareware and other extraneous software.