

LANCOM Release Notes

LANtools 10.34 Rel

Copyright (c) 2002-2020 LANCOM Systems GmbH, Wuerselen (Germany)

LANCOM Systems GmbH
Adenauerstrasse 20 / B2
52146 Wuerselen
Germany

Internet: <http://www.lancom-systems.com>

April 24th, 2020, CBuersch

Table of Contents

| | |
|--|----------|
| 1. Preface | 2 |
| 2. New features, improvements, and history | 3 |
| LANconfig 10.34.0016 Rel / LANmonitor 10.34.0004 Rel | 3 |
| Important advice | 4 |
| Disclaimer | 4 |

1. Preface

The LANtools are a comprehensive set of free management & monitoring tools for a detailed configuration and monitoring of LANCOM devices.

This document describes the innovations within LANtools version 10.34 Rel, as well as the improvements since the previous version.

Note

LANCOM LANtools support Windows 7, Windows 8, Windows 10, Windows 2008 Server, Windows Small Business Server 2011, Windows Server 2012, Windows Server 2012 R2, and Windows Server 2016 (all 32- and 64-bit versions).

For Windows Vista and Windows 2008 Server you will find user data under \Users\USER\AppData\Roaming\LANCOM\ and the application files under \ProgramData\LANCOM\.

When upgrading to LANtools 8.50 or newer, all existing user- and application data is moved to the corresponding folders.

2. New features, improvements, and history

LANconfig 10.34.0016 Rel / LANmonitor 10.34.0004 Rel

Bugfixes / improvements

LANmonitor

- › No PoE data was displayed in LANmonitor for the switch LANCOM GS-3152XP.
- › The LANCOM LW-500 could not be displayed in LANmonitor.
- › LANmonitor displayed inaccurate date and time values for the IPv4- and IPv6 firewall entries.

Important advice

Disclaimer

LANCOM Systems GmbH does not take any guarantee and liability for software not developed, manufactured or distributed by LANCOM Systems GmbH, especially not for shareware and other extraneous software.