

Information for

LANCOM Management System (LCMS) Version 8.60 RU1

Copyright (c) 2002-2012 LANCOM Systems GmbH, Wuerselen (Germany)

LANCOM Systems GmbH does not take any guarantee and liability for software not developed, manufactured or distributed by LANCOM Systems GmbH, especially not for shareware and other extraneous software.

LANCOM Systems GmbH Adenauerstrasse 20 / B2 52146 Wuerselen Germany

Internet: http://www.lancom.eu

17.04.2012, CBuersch

Table of Contents

1.	Preface	2
	Note	
2.	New Features, Changes and History	
	LANconfig changes 8.60.0062 Release ► 8.60.0063 RU1	
	LANconfig changes 8.60.0057 RC3 ▶ 8.60.0062 Release	
	LANmonitor changes 8.60.0026 RC3 ▶ 8.60.0031 Release	
	LANconfig changes 8.60.0045 RC2 ▶ 8.60.0057 RC3	
	LANmonitor changes 8.60.0018 RC2 ▶ 8.60.0026 RC3	
	LANconfig changes 8.60.0035 RC1 ▶ 8.60.0045 RC2	
	LANmonitor changes 8.60.0011 RC1 ▶ 8.60.0018 RC2	
	LANconfig changes 8.50.0074 RU2 ▶ 8.60.0035 RC1	6
	LANmonitor changes 8 50 0033 RU1 ▶ 8 60 0011 RC1	



1. Preface

LCMS, consisting of LANconfig and LANmonitor, serves for the administration of all Wireless LAN Access Points and Routers. The at a time latest versions are available for all LANCOM products. You can download it for free at http://www.lancom-systems.com

This document describes the innovations within version 8.60 RU1, as well as the modifications since version 8.50.

Note

LCMS supports Windows XP, Windows Vista, Windows 7, Windows 2003 Server and Windows 2008 Server (all 32- and 64-bit versions).

As from version 8.50 the paths for user data and application data have changed. In Windows XP and Windows 2003 Server you will find user data under \Documents and Settings\USER\Application Data\LANCOM\ and the application files under \Documents and Settings\All Users\Application Data\LANCOM\.

For Windows Vista and Windows 2008 Server you will find user data under \Users\USER\AppData\Roaming\LANCOM\ and the application files under \ProgramData\LANCOM\.

When upgrading to version 8.50 or newer existing user data and application data are moved to the corresponding folders.



2. New Features, Changes and History

LANconfig changes 8.60.0062 Release ▶ 8.60.0063 RU1

Bugfixes / Changes:

LANconfig:

When using the VPN wizard, the configuration of a VPN client dial-in does no longer lead to a device reboot

LANconfig changes 8.60.0057 RC3 ► 8.60.0062 Release LANmonitor changes 8.60.0026 RC3 ► 8.60.0031 Release

Bugfixes / Changes:

LANconfig:

- For Windows users with limited access status information is displayed again
- The Internet wizard creates a particular communication layer for a DHCP connection
- The remove wizard now deletes firewall rules which were added by the installation wizard, too
- Firewall rules can be configured with group configurations

LANmonitor:

ADSL SNR is displayed as "Not available" if the corresponding LCOS values are not present



<u>LANconfig changes 8.60.0045 RC2</u> ► 8.60.0057 RC3 <u>LANmonitor changes 8.60.0018 RC2</u> ► 8.60.0026 RC3

New Features:

LANconfig:

NAT-Traversal is activated by the VPN wizard

LANmonitor:

- The IMEI of the mobile radio modem is shown
- SIM card state is shown
- Particular icons for faulty but connected VPN tunnels

Bugfixes / Changes:

LANconfig:

- The internet wizard for provider RH-TEC adds the user suffix only if it was not already specified
- If an error is recognized in a firewall object, cancelling the dialogue does no longer leave the firewall object in a non-editable state
- The remove wizard does not remove VPN proposal lists if they are still used by default parameters
- No option to start LANmonitor from the context menu for serial-connected devices
- Enlarged display of the password data fields
- A group configuration can be deleted by using the DEL key, too
- If some of the selected devices are not accessible, a manual "search for updates" always returns the correct result
- WLAN profile settings of a WLC can be stored to a group configuration
- The backup table of a WLC-4006 can be configured using LANconfig
- A configuration change warning when closing the configuration is only displayed if configuration changes were made
- Private mode configurable for devices LANCOM 1681V, LANCOM 831A, LANCOM 1631E and LANCOM 1781
- Customized communication layers for LANCOM 1681V
- The RADIUS client password can be configured full-length from within LANconfig

LANmonitor:

- Changes in the WLC station table are displayed immediately
- Throughput scale auto adoption



<u>LANconfig changes 8.60.0035 RC1</u> ► 8.60.0045 RC2 <u>LANmonitor changes 8.60.0011 RC1</u> ► 8.60.0018 RC2

New Features:

LANconfig:

- Internet access for provider RH-TEC is configurable via Internet wizard
- The T-DSL Business internet wizard recognizes pre- and postfixes in user data and in this case does not add this data by itself

LANmonitor:

Mobile radio parameters are now available in the root directory

Bugfixes / Changes:

LANconfig:

- When using the default button the MAC address is preallocated in the WLC access point table
- The UMTS wizard sets the 'short hold time 2' in the remote station table accurately
- The DSLoL interface of the LANCOM IAP-321 can be configured for LAN-2, too
- After having typed an incorrect LANCOM option license key the error message shows up only once
- Manual group configuration refresh is possible via context menu
- The value of the 'Absolue Expiry' field is stored accurately
- Selectable SSL encapsulation in the VPN wizard
- Configurable SIP user authentication via WAN/VPN
- No more application crash when using the link "Why is my device not listed here" from within the Auto Updater
- Inactive parameters in static tables can be defined as group parameters

LANmonitor:

- PIN requirement of a UMTS card is shown in LANmonitor
- Maximum up- and downstream rate of a UMTS connection is displayed
- SIP users are shown which connection type (WAN, VPN) is possible for authentication, and if access is already blocked due to failed attempts



<u>LANconfig changes 8.50.0074 RU2 ► 8.60.0035 RC1</u> <u>LANmonitor changes 8.50.0033 RU1 ► 8.60.0011 RC1</u>

New Features:

LANconfig:

- Fields "Location" and "Comment 1" are displayed as device detail
- Definable group configuration fields
- The device list can be exported to a .CSV file
- Devices can be imported to LANconfig using a .CSV file
- Default VPN lifetimes adopted to new LCOS values
- Seamless Roaming activated by default in the LANconfig-generated profile for the LANCOM Advanced VPN Client

LANmonitor:

- A faulty WLAN controller configuration is displayed in LANmonitor
- Improved keyboard control
- IPsec over HTTPS connections are displayed in tree view

Bugfixes / Changes:

LANconfig:

- If a device was found by Quickfinder, it is now possible to move the device to any other folder
- The first device in the list is now checked in flatview mode, too
- Source and target of the firewall rules are checked already when opening the firewall settings
- No more SNMP-IDs when printing a configuration
- Configurable monitor mode for new devices with gigabit switch
- Firewall objects are no longer limited to 63 characters
- Serial LCOS upload works again for a LANCOM 1781A-3G
- Improved automatic network mask calculation
- Configurable maximum size for the Public Spot station table

(W)LANmonitor:

- The VPN client serial number is only displayed with a LANCOM Advanced VPN client dial-in
- No refresh necessary for displaying the QoS branch on a LANCOM 1681V
- If a new accesspoint authenticates at the WLAN controller, the branch "New APs" can be expanded without prior refresh
- WLANmonitor causes no application hang if it was invoked by LANconfig and no password was stored for the monitored WLAN device in the device properties
- Corrected D-channel protocol display