

Information regarding

LANCOM Management System (LCMS) Version 9.18 Rel

Copyright (c) 2002-2015 LANCOM Systems GmbH, Wuerselen (Germany)

LANCOM Systems GmbH does not take any guarantee and liability for software not developed, manufactured or distributed by LANCOM Systems GmbH, especially not for shareware and other extraneous software.

LANCOM Systems GmbH
Adenauerstrasse 20 / B2
52146 Wuerselen
Germany

Internet: <http://www.lancom.eu>

28.08.2015, MPlum

Table of Contents

1. Preface	2
Note	2
2. New Features, Improvements and History	3
LANconfig improvements 9.10.0087 Rel ▶ 9.18.0016 Rel	3
LANmonitor improvements 9.10.0073 Rel ▶ 9.18.0010 Rel.....	3
LANconfig improvements 9.10.0063 RC2 ▶ 9.10.0087 Rel.....	3
LANmonitor improvements 9.10.0056 RC2 ▶ 9.10.0073 Rel	3
LANconfig improvements 9.10.0053 RC1 ▶ 9.10.0063 RC2.....	4
LANmonitor improvements 9.10.0050 RC1 ▶ 9.10.0056 RC2	4
LANconfig improvements 9.04.0057 RU3 ▶ 9.10.0053 RC1.....	4
LANmonitor improvements 9.04.0025 RU3 ▶ 9.10.0050 RC1	4

1. Preface

LCMS, consisting of LANconfig and LANmonitor, serves for the administration of all Wireless LAN Access Points and Routers. The at a time latest versions are available for all LANCOM products. You can download it for free at <http://www.lancom-systems.com>

This document describes the innovations within version 9.18 Rel, as well as the modifications since version 9.10.

Note

LCMS supports Windows Vista, Windows 7, Windows 8, Windows 10, Windows 2003 Server, Windows 2008 Server, Windows Server 2011 (all 32- and 64-bit versions) and Windows Server 2012 & Windows Server 2012 R2.

For Windows Vista and Windows 2008 Server you will find user data under \Users\USER\AppData\Roaming\LANCOM\ and the application files under \ProgramData\LANCOM\.

When upgrading to version 8.50 or newer existing user- and application data is moved to the corresponding folders.

2. New Features, Improvements and History

LANconfig improvements 9.10.0087 Rel ► 9.18.0016 Rel LANmonitor improvements 9.10.0073 Rel ► 9.18.0010 Rel

New Features:

LANconfig:

- Support for new devices: LANCOM 1783VA, 1783VAW, LN-830acn dual Wireless, L-822acn dual Wireless, OAP-821, OAP-822, OAP 830.
- All-IP wizard for LANCOM 1783VA/VAW added.
- Support of Feature „Adaptive RF Optimization“.
- Support of Feature “Wireless Intrusion Detection System (WIDS)”.
- Support of Feature “Airtime Fairness”.

Bugfixes / Improvements:

LANconfig:

- Shorter units for Public-Spot expiration times are added.

(W)LANmonitor:

- WiFi quality index now is shown below the WiFi network display.

LANconfig improvements 9.10.0063 RC2 ► 9.10.0087 Rel LANmonitor improvements 9.10.0056 RC2 ► 9.10.0073 Rel

New Features:

LANconfig:

- While creating an offline configuration, LCOS versions can now be sorted.
- The ordering of device types for the firmware management with a WLC has been adjusted.
- Wildcards can be used within the Circuit ID.
- Firmware updates for newly found devices can now be searched for directly.

Bugfixes / Improvements:

LANconfig:

- For devices without SCEP-CA the settings for WEB-CA are displayed again on the designated location.
- A problem has been fixed which caused the trace module to crash.
- The summary of the Public Spot wizard will now display the actual configuration.
- If a certificate-based VPN client dial-in is configured via wizard, the corresponding INI file will be created correctly.

(W)LANmonitor:

- The IPv6 address of a client is displayed correctly.
- Switches with a Get community other than "public" can be monitored.
- There was a bug which caused the LANmonitor to crash after multiple executions of the radio field optimization.

LANconfig improvements 9.10.0053 RC1 ► 9.10.0063 RC2
LANmonitor improvements 9.10.0050 RC1 ► 9.10.0056 RC2

New Features:

LANconfig:

- Interface assignment "Any" was removed.
- Offline configurations can now be sorted by LCOS version.

Bugfixes / Improvements:

LANconfig:

- A problem was solved that caused that LANconfig crashed when using the Setup Wizard to remove a remote site.
- If new WWAN remote station is created with the setup wizard, the SIM profiles are now called as the associated WWAN remote station.

(W)LANmonitor:

- RSTP (Rapid Spanning Tree) is displayed correctly.
- All configured WLAN SSIDs are displayed.

LANconfig improvements 9.04.0057 RU3 ► 9.10.0053 RC1
LANmonitor improvements 9.04.0025 RU3 ► 9.10.0050 RC1

New Features:

LANconfig:

- MAC addresses can be entered in the usual notation now.
- The setup wizard for Internet access and DynDNS provider has been extended.

(W)LANmonitor:

- MAC addresses are now displayed with the manufacturer ID.
- The number of available and used Public Spot accounts is now displayed.