

Information regarding
LANCOM ES-2126P+

Copyright (c) 2002-2011 LANCOM Systems GmbH, Wuerselen (Germany)

LANCOM Systems GmbH does not take any guarantee and liability for software not developed, manufactured or distributed by LANCOM Systems GmbH, especially not for shareware and other extraneous software.

LANCOM Systems GmbH
Adenauerstrasse 20 / B2
52146 Wuerselen
Germany

Internet: <http://www.lancom.eu>

23.04.2013, MPlum

Table of Contents

1. Hints
2. New Features, Changes and History

1. Hints

Hint when using Firefox 3 for configuration

In Firefox 3 there is a problem with the interpretation of the SSL certificate.
Further information regarding this problem can be found under the following link:
https://bugzilla.mozilla.org/show_bug.cgi?id=435013

2. New Features, Changes and History

LANCOM ES-2126P+ changes 5.04 Release → 5.20 Release

New Features:

- Added standard login fallback method for TACACS+

Bugfixes / Changes:

- Modified 'Virtual Stack' page in WEBconfig
- Corrected 'Virtual Stack' display
- After enabling the 'Virtual Stack' function in WEBconfig the function is activated immediately
- When using TACACS+, a 'Virtual Stack Fail' does no longer lead to an instant logout
- Improved loopback functionality